

Message

From: Barnett, Thomas R [Thomas.Barnett@arcelormittal.com]
Sent: 3/30/2017 8:34:31 PM
To: sean.fitzgerald@uscg.mil; Beslow, Mike [beslow.mike@epa.gov]
CC: David Greinke (DGREINKE@idem.IN.gov) [DGREINKE@idem.IN.gov]; nream@idem.IN.gov
Subject: Outfall and sump reports, thursday, March 30, 2017
Attachments: img-330153505-0001.pdf; 910.jpg; 001.jpg; 001city.jpg

Heavy rains today. Sheen inside the steel weir at 001, and some sheen outside the weir, inside the soft booms. 001city.jpg is the City sanitary overflow, which was contributing to the sheen outside the steel weir.

Diver is tentatively scheduled for Friday the 7th to inspect the 001 outfall, will confirm by Wednesday.

Sean, we are in receipt of the letter from Commander Merchant.

Thomas Barnett | Manager, Environmental Technology
ArcelorMittal Indiana Harbor LLC.
ArcelorMittal USA LLC

Environmental Department | 3001 Dickey Road, Sta. 001
East Chicago, IN 46312

T +219 399 2380 | M +219 313 1605 | F +219 399 3211 | www.arcelormittal.com

-----Original Message-----

From: WorkCentre 5225 [mailto:mailto:no-reply@arcelormittal.com]
Sent: Thursday, March 30, 2017 3:35 PM
To: Barnett, Thomas R <Thomas.Barnett@arcelormittal.com>
Subject: Scan from a Xerox WorkCentre

Please open the attached document. It was scanned and sent to you using a Xerox WorkCentre.

Number of Images: 3
Attachment File Type: PDF

Device Name: WorkCentre 5225
Device Location:

For more information on Xerox products and solutions, please visit <http://www.xerox.com/>